



Cable track broken from solder joint to pin 34

Cable soldered from pin 34 to 5th pin on header cable

000 resistor moved from jc31 to jc30

Cable soldered from solder joint to pin 2 on cable connector

Solder blob placed to connect sw3, at top of drive

