


Cable soldered from dc connection to pin 2



000 resistor moved from dc to RDY

Ds1 connection broken and ds0 connection made